













KOMMODE/ COMMODE/ CHEST OF DRAWERS



MODEL: FLINT











A		12	B		12	C		6
D		8	F		24	G		22
K_L		3	K_R		3	L		
M		3	O		8	P		9









3xA





6xB








6xA




8xO








22xG





1xL




3xK_R




12xF








3xK_L



12xF



1xM



3x

